Qty:

1 Um:

Each

: FWD X-TUBE

: D2889 REV B

: 30/05/2008

: D2889

: N/A

: B

Date:

Thursday, 17/04/2008 10:59:27 AM

User:

Julie Lecocq

## **Process Sheet**

**Drawing Name** 

**Part Number** 

Material **Due Date** 

**Drawing Number** 

**Project Number** 

**Drawing Revision** 

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number **Estimate Number**  : 38663

P.O. Number

Prsht Rev.

First Issue

**Previous Run** 

This Issue

: 17/04/2008

: 10006

: NC

: //

Type

: LANDING GEAR

: 38561

Written By Checked & Approved By

Comment

: Est Rev:A

New Issue 05-10-25 JLM

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description: Crosstube Material

D6005180 1.0



Comment: Qty.:

1.0000 Each(s)/Unit Total:

1.0000 Each(s)

Crosstube material

Pick:

Qty Part number 1 D2889

Description

Fwd Crosstube

Batch


BENDING MACHINE - SKIDTUBES

BENDING 2.0



**Comment: LANDING GEAR RESOURCE 1** 

1-Bend D2889 as per Dwg D2889 and Folio FT001



3.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Deburr and Polish

QC15

DIMENSIONAL CHECK OF X-TUBES

Comment: DIMENSIONAL CHECK OF X-TUBES

5.0

4.0

HAND FINISHING1

HAND PINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and alodine as per QSI 005 4.1.

Inside and outside of tube



Page 1

Form: rprocess

## **Dart Aerospace Ltd**

	WORK ORDER CHANGES						
STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	STEP						Approval

Part No:	PAR #:	Fault Category:	NCR: Yes N	lo DQA:	Date:
			QA: N/	C Closed:	Date:

NCR:		,	WORK ORD	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section B	tive Action Section B		Annroyal	Annroyal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
•								
						1		

NOTE: Date & initial all entries

Date: User:

Thursday, 17/04/2008 10:59:27 AM

Julie Lecocq

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FWD X-TUBE

Job Number: 38663

Part Number: D2889

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

7.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: <u>W/0</u> 37903 (-101)

8.0



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



## **Dart Aerospace Ltd**


<b>W</b> /O:		WORK OF	DER CHAN	GES				
DATE	STEP	PROCEDURE CHANGE	:	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
ı								
			-					
<u>.</u>			·					
Part No	:	PAR #: Fault Category:		NCR: Yes	No DQ	A:	Date:	
ı				QA: I	N/C Close	d:	Date:	

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
<u>;</u>		Description of NC		Corrective Action Section B		Verification	Annuara	Ammasial
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
								-

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	30/063
Description: Crosstube Fwd	Part Number:	D2889
Inspection Dwg: D2889 Rev: B		Page 1 of 1

Required Dimension	Min	Max
Height	49.875	50.125
1/2 Span	69.275	69.525
Angle	49	52
Total Span	138.55	139.05



	Comments	
		<del></del>
	1	
QC15 Inspection		
Date	0808-12	

Rev	Date	Change	Revised b	y	Apprøved
Α	07.02.06	New Issue	KJ/JM ↔	4	fr
	<u>.</u>		- 1	J	

